



Lyndon W. Herrstrom, CPM<sup>®</sup>, PE, Facility Manager  
8760-A Research Boulevard, Suite 496 • Austin, TX, 78758  
Phone: 512.278.7390 • Fax: 512.272.3049  
[lyndon\\_herrstrom@contractor.amat.com](mailto:lyndon_herrstrom@contractor.amat.com)

September 2, 2005

Mr. Tom Mayfield  
Mayfield Thermography

Re: Infrared Scan at Applied Materials, Austin, Texas

Dear Tom:

As a follow-up to our conversation, regarding the results of your infrared scan, we are very pleased with the results. The results concurred with core samples taken prior to the infrared scan and also highlighted some other areas that we did not find with random coring. Our plan for repair and replacement, following the March 25 F-0 tornado that tore through the site, has been formulated largely from the results of the scan.

How refreshing and how convenient it has been to send you an electronic CAD drawing and have you overlay the results via CAD.

While we do not look forward to another tornado, we do look forward to doing business again in the future.

Sincerely,  
LINC FACILITY SERVICES, LLC

A handwritten signature in black ink that reads "Lyndon W. Herrstrom".

Lyndon W. Herrstrom, CPM<sup>®</sup>, PE  
Facility Manager